

CENTRAL INTELLIGENCE AGENCY
INFORMATION REPORT

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Sec. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

25X1

SECRET/U.S. OFFICIALS ONLY

COUNTRY	Poland	REPORT	
SUBJECT	Ship Repair Yard at Gdynia	DATE DISTR.	23 February 1955
DATE OF INFO.		NO. OF PAGES	1
PLACE ACQUIRED		REQUIREMENT NO.	RD 25X1
		REFERENCES	

This is UNEVALUATED Information

THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE.
 THE APPRAISAL OF CONTENT IS TENTATIVE.
 (FOR REF SEE REVERSE)

1. The layout of the small ship repair yard in No. 2 Basia, Gdynia, cannot be clearly seen from No. 3 Basia. 25X1
2. There is a small pontoon alongside the inner end of the Silesian Quay. This pontoon has a lifting capacity for ships of 2,000 to 3,000 tons d.w.
3. At the outer end of the Silesian Quay were two merchant ships. One ship was a Polish cargo ship of 5,000 to 6,000 tons d.w. undergoing repairs. The other ship was a salvaged Blue Star ship which was originally built in Denmark and then captured by the Germans. This ship was about 17,000 tons and was being rebuilt for the Russians. 25X1

25X1

25X1

25X1

25X1

SECRET/U.S. OFFICIALS ONLY

STATE	X	ARMY	X	NAVY	X	AIR	X	FBI		NSC							
-------	---	------	---	------	---	-----	---	-----	--	-----	--	--	--	--	--	--	--

(NOTE: Washington distribution indicated by "X"; Field distribution by "O")